

OFFICE OF THE MARION COUNTY SURVEYOR

SECTION RECORD CORNER

SECTION 13 TOWNSHIP 17 RANGE 3

DATE: 9-22-08

PARTY CHIEF: Wilcoxon

CREW: _____

TYPE OF MARKER: Harrison marker



METHOD OF ESTABLISHMENT: County: 7-10-02

IN. S.P.C. E ZONE NAD '83

NAME: 17031304

N: 518726.4740(m)

E: 59033.1130(m)



CORNER HISTORY: Original post set 1820 by Laughlin with witness: 14" hickory S 13 W 15 links; 12" ash N 88 W 14 links per Marion County Atlas pg. 8. Records called no stone nor witness per Washington Township Legal Survey Book. Hankins 4-3-58 called cut 'x' in concrete pavement. MCSO 1963 called same. Miller 1-26-76 called the same. Miller 8-17-78 and no cut 'x' fd. Re-set railroad spike at surface per '76 ties. Bruer 10-25-79 called RR spike. Excavated by Wilcoxon 4-5-83, RR spike fd at surface. Another RR spike fd 4" dn. Both RR spikes were .12' NE of old ties. No stone fd. Excavated 1986 during construction Harrison set. Re-tied 3-7-97 by Wilcoxon. Re-tied by Wilcoxon 7-10-02. Updated and added new riser because of re-surfacing, 9-22-08 by Wilcoxon.

17031404

REF.	DISTANCE	DESCRIPTION
1.	64.15'	Top nut of fire hydrant
2.	64.72'	Cut 'x' SF-bolt of aluminum pole base
3.	74.72'	Northerly corner of brick column
4.	57.46'	Cut 'x' SW-bolt of aluminum pole base #437-207A
5.	62.00'	Cut 'x' SF-bolt of aluminum pole base
6.	54.53'	Cut 'x' SW-bolt of aluminum pole base